


CC41-Cable to Cable

Run mm ²	Tap mm ²	Welding Powder	Mould
10	10	USE MOULD TYPE CC4 ON PAGE 72	
10	16	USE MOULD TYPE CC4 ON PAGE 72	
10	25	USE MOULD TYPE CC4 ON PAGE 72	
16	10	USE MOULD TYPE CC4 ON PAGE 72	
16	16	USE MOULD TYPE CC4 ON PAGE 72	
16	25	USE MOULD TYPE CC4 ON PAGE 72	
25	10	USE MOULD TYPE CC4 ON PAGE 72	
25	16	USE MOULD TYPE CC4 ON PAGE 72	
25	25	USE MOULD TYPE CC4 ON PAGE 72	
35	10	USE MOULD TYPE CC4 ON PAGE 72	
35	16	USE MOULD TYPE CC4 ON PAGE 72	
35	25	USE MOULD TYPE CC4 ON PAGE 72	
35	35	KWD 090	CC41-035-035
50	35	KWD 115	CC41-050-035
50	50	KWD 150	CC41-050-050
70	35	KWD 150	CC41-070-035
70	50	KWD 200	CC41-070-050
70	70	KWD 200	CC41-070-070
95	35	KWD 200	CC41-095-035
95	50	KWD 200	CC41-095-050
95	70	KWD 250	CC41-095-070
95	95	KWD 250	CC41-095-095
120	50	KWD 250	CC41-120-050
120	70	KWD 250	CC41-120-070
120	95	2xKWD 150	CC41-120-115
120	120	2xKWD 150	CC41-120-120
150	70	KWD 250	CC41-150-070
150	95	2xKWD 150	CC41-150-095
150	120	2xKWD 200	CC41-150-120
150	150	2xKWD 200	CC41-150-150
185	70	2x KWD 200	CC41-185-070
185	95	2x KWD 200	CC41-185-095
185	120	2x KWD 250	CC41-185-120
185	150	2x KWD 250	CC41-185-150
185	185	2x KWD 250	CC41-185-185



Handle clamp : HC 02 is suitable for these moulds

Attention:

1- Our routine sizes and weld connections are listed in this catalogue; for other types and sizes please contact our sales office.